PHOTO REPORT OF GEOTECHNICAL STUDY AT BURWASH LANDING AND DESTRUCTION BAY

252 HARDY 1983



M.P. 1087.5
TH 1

View from Highway
Looking North



M.P. 1067.5

View to east of cut
in area of TH 2



M.P. 1086.2

View to N.W approx. from THC-13

Photos 4 & 5



M.P. 1086.2 Photos looking east to intersection of Power-Line, Highway and trail (BHC-1) to site



M.P. 1086.2

TH C5



Photo #1

M.P. 1086.2

Cut near TH C-6
(Just east of THC6)



Photo 12

M.P. 1086.6
TH C-8



M.P. 1095.1

TH B-11

View looking South

Photo #17



M.P. 1095.1

TH 15

View looking south

PHOTO 18



M.P. 1086.2

TH C3

PHOTO 10



M.P. 1095-1
Cut near B 3



photo 10

M.P. 1095.1

TH B3 & B4
View looking east



Photo 11

M.P. 1095. 1
Cut near TH B 10




Photo 16

M.P. 1087.5
TH A6
View looking south
(back to highway)
Photo 4



M.P. 1087.5
TH A7
Looking south towards
highway



M.P. 1087.5
Climbing Hill
to TH A4



MP. 1087.5
TH A-9
View from pit looking east



photo 8

MP. 1087.5
TH A-10
View from edge of highway looking North



photo 9

M.P. 1087.5
View looking east along highway
Site is on the left



M.P. 1057.5

TH A-1

view looking North



Photo 22

MP 1087.5
TH A2
View to North from edge of highway



MP 1087.5
TH. A3
View looking east from pit



Photo 24

M.P. 1095.1

TH 9

View to South

photos 14 & 15





M.P. 1086.2

Old Dump Site

photos 1, 2





M.P. 1086.2
TH C10

View looking north From south edge of existing pit.


Photos 15 816



M.P. 1086.2

Cut on west side of Pit

Photos 13 & 14



M.P. 1095.1

Photo Panorama
Drilling rig at TH B12
View looking south

